

## ***Pressure sensor complete cable – 30 m***

### **1. Connector JUPITER 10 TP**



### **2. Cable „LAPP“ KABEL OLFLEX ROBOT 900 DP 4x0,34 RoHS - lenght 30 m**



### 3. Connector ILME CKM 03 (CKSM 03)



### 4. HOODS MKVA V20 and CAPS CKAX 03 CXA



CABLE GLAND M20x 1,5

